


1/8" Jack x 4



Pot 1k



Pot 10k x 2



Pot 100k




Pot 1M



10-turn pot (2k) with nut and washer




Small Knob x 5




Big Knob




10-16 pin ribbon cable with connectors



SPDT flip x 3




Hex nuts for Pots x 5



Washers for Pots x 5



Panel, 16HP



PCB

